

April 09, 2024 Diane Czarnecki Industrial Hygienist Facilities Management Division GSA Public Buildings Service – Heartland Region 2300 Main Street Kansas City, MO 64108

Re: Goodfellow Federal Center – Bldg. 105L Drinking Water Sampling Project No. 121244

Dear Ms. Czarnecki:

Thank you for the opportunity to provide the General Services Administration (GSA) with the above referenced environmental sampling activities. The following is our report.

#### **INTRODUCTION**

As requested, Burns & McDonnell conducted drinking water sampling and testing for the presence of lead and copper at Building 105L of the Goodfellow Federal Center located at 4300 Goodfellow Boulevard in St. Louis, Missouri. Sampling was completed in response to the ongoing environmental condition assessment at the Goodfellow Federal Center.

Drinking water sampling was conducted to determine the current levels of lead and copper in representative sources throughout the complex. Drinking water sampling at Bldg. 105L was conducted on March 12, 2024 by Ashley Anstaett & Tasnima Uddin of Burns & McDonnell.

#### METHODOLOGY

The sampling methodology used during this investigation was developed in general accordance with the United States Environmental Protection Agency's (EPA) "Quick Guide to Drinking Water Sample Collection – Second Edition" developed by the EPA Region 8 in September 2016.

Samples were collected as first draw samples in accordance with the Lead and Copper Rule (40 CFR Part 141 Subpart I). First draw samples represent 'worst case' conditions with water that has been stationary within the plumbing systems for a minimum of six hours. The samples were collected in individually labeled 1000 milliliter (mL) plastic bottles capped with Teflon septa lined screw caps. The bottles were filled to the shoulder with water from the sample source. The samples were then placed in a cooler for safe transport. Each sample was acidified at the laboratory as needed.

Drinking water sampling for the presence of lead and copper was conducted at one (1) distinct locations within Building 105L. A total of two (2) samples were obtained including duplicate samples. After each drinking water sample was collected, Burns & McDonnell filled a separate sample cup with approximately 2 inches of water. Burns & McDonnell placed an Oakton pH30 pH tester into the sample cup. After readings stabilized, Burns & McDonnell recorded the



Diane Czarnecki Facilities Management Division April 09, 2024 Page 2

readings for pH (the acidity or basicity of an aqueous solution) and the temperature (in degrees Celsius) on site specific sample logs.

Drinking water samples were submitted to Eurofins-Eaton Analytical in South Bend, IN for analyses of lead and copper. Eurofins-Eaton Analytical is certified by the State of Missouri Department of Natural Resources (MDNR) as an approved drinking water laboratory. Eurofins-Eaton Analytical's Missouri Certification number is 880.

The drinking water samples were collected using media supplied by Eurofins-Eaton Analytical. Lead and Copper samples were collected and analyzed in accordance with EPA Method 200.8.

#### **RESULTS AND DISCUSSION**

The results for the subject testing are summarized in the table below.

Analysis	Lowest Concentration <sup>(a)</sup>	Highest Concentration <sup>(a)</sup>	Action Level <sup>(b)</sup>
Lead	0.95 μg/L	1.00 µg/L	15 μg/L
Copper	31 µg/L	32 µg/L	1300 µg/L

Notes:

(a) Samples with a "<" sign indicate that the results were below the reportable limit.

(b) As per EPA Lead and Copper Rule (40 CFR Part 141 Subpart I).

(c)  $\mu g/L$  – micrograms per liter

No samples resulted in levels over the action levels, 15  $\mu$ g/L for lead and 1,300  $\mu$ g/L for copper.

A summary table of all sampling results by location is included in Appendix A. The complete laboratory report for the drinking water sampling from Eurofins-Eaton Analytical is attached in Appendix B.

#### pН

Normal pH levels for drinking water are between 6.0 to 8.5. Water with a pH < 6.5 is considered acidic, soft, and corrosive. Acidic water may contain metal ions, may cause premature damage to metal piping, and increases the likelihood of leaching. Water with a pH > 8.5 is considered alkaline or basic and can indicate that the water is hard. Hard water does not pose a health risk but can cause aesthetic problems. These problems include an alkali taste, the formation of scale deposits, and difficulty in getting soaps and detergents to lather.

Recorded pH levels in Building 105L ranged from 10.20 to 10.20 indicating the drinking water is slightly alkaline.



Diane Czarnecki Facilities Management Division April 09, 2024 Page 3

#### LIMITATIONS

The scope of this assessment was limited in nature. Burns & McDonnell collected samples from a select number of drinking water sources in an effort to minimize cost while providing a general overview of the drinking water quality at the site. Sample locations do not encompass every drinking water source at the Site. Additionally, samples were only analyzed for a select number of potential contaminants likely to affect the drinking water quality at the site. Burns & McDonnell is not responsible for potential contaminants not identified in this report.

Burns & McDonnell appreciates the opportunity to work with the GSA on this project. Please contact us if you have any questions regarding this report or if we may be of any additional service.

Sincerely,

Matt Shanahan, CHMM Project Manager

Attachments:

Appendix A - Results Summary by Location Appendix B - Water Sample Laboratory Report **APPENDIX A – RESULTS SUMMARY BY LOCATION** 

### Appendix A Results Summary by Location

Sample Number	Location	рН	Temp (°C)	Water Source	Analyte	Result	Units	Above / Below	AL
105L-DW-01	South hallway DF	10.2	16.7	DF	Copper	32	μg/L	Below	1300
105L-DW-01	South hallway DF	10.2	16.7	DF	Lead	1.0	μg/L	Below	15
105L-DW-02	Duplicate of 105L-DW-01	10.2	16.7	DF D	Copper	31	μg/L	Below	1300
105L-DW-02	Duplicate of 105L-DW-01	10.2	16.7	DF D	Lead	0.95	μg/L	Below	15

Notes:

DF - Drinking Fountain

D - Duplicate

L/R - Left or Right

**Dil - Dilution** 

AL - Action Level

µg/L - micrograms per liter

APPENDIX B – WATER SAMPLE LABORATORY REPORT



**Environment Testing** 

# **ANALYTICAL REPORT**

## PREPARED FOR

Attn: Mr. Matt Shanahan Burns & McDonnell 425 South Woods Mill Road Suite 300 Chesterfield, Missouri 63017 Generated 3/20/2024 2:18:22 AM

### JOB DESCRIPTION

GFC

### JOB NUMBER

810-97545-1

Eurofins Eaton Analytical South Bend 110 S Hill Street South Bend IN 46617





### **Eurofins Eaton Analytical South Bend**

### Job Notes

This report may not be reproduced except in full, and with written approval from the laboratory. The results relate only to the samples tested. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.

The test results in this report relate only to the samples as received by the laboratory and will meet all requirements of the methodology, with any exceptions noted. This report shall not be reproduced except in full, without the express written approval of the laboratory. All questions should be directed to the Eurofins Eaton Analytical, LLC Project Manager.

### Authorization

(b) (6)

Generated 3/20/2024 2:18:22 AM 1

Authorized for release by Amanda Scott, Project Manager <u>Amanda.Scott@et.eurofinsus.com</u> (574)233-4777

# **Table of Contents**

Cover Page	1
Table of Contents	3
Definitions/Glossary	4
Case Narrative	5
Client Sample Results	6
Lab Chronicle	7
Certification Summary	8
Method Summary	9
Sample Summary	10
Chain of Custody	11
Receipt Checklists	12

#### Client: Burns & McDonnell Project/Site: GFC

Percent Recovery

Contains Free Liquid

Colony Forming Unit

Glossary Abbreviation

¤ %R

CFL

CFU

Job ID: 810-97545-1	2
	3
	4
	5
	6
	7
	8
	9
	10
	11

CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MCL	EPA recommended "Maximum Contaminant Level"
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
MPN	Most Probable Number
MQL	Method Quantitation Limit
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
NEG	Negative / Absent
POS	Positive / Present
PQL	Practical Quantitation Limit
PRES	Presumptive
QC	Quality Control
RER	Relative Error Ratio (Radiochemistry)
RL	Reporting Limit or Requested Limit (Radiochemistry)
RPD	Relative Percent Difference, a measure of the relative difference between two points
TEF	Toxicity Equivalent Factor (Dioxin)
TEQ	Toxicity Equivalent Quotient (Dioxin)
TNTC	Too Numerous To Count

These commonly used abbreviations may or may not be present in this report. Listed under the "D" column to designate that the result is reported on a dry weight basis

#### Job ID: 810-97545-1

#### **Eurofins Eaton Analytical South Bend**

#### Job Narrative 810-97545-1

Analytical test results meet all requirements of the associated regulatory program listed on the Accreditation/Certification Summary Page unless otherwise noted under the individual analysis. Data qualifiers are applied to indicate exceptions. Noncompliant quality control (QC) is further explained in narrative comments.

- Matrix QC may not be reported if insufficient sample or site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD may be performed, unless otherwise specified in the method.
- Surrogate and/or isotope dilution analyte recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in the narrative.

Regulated compliance samples (e.g. SDWA, NPDES) must comply with the associated agency requirements/permits.

#### Receipt

The samples were received on 3/18/2024 9:00 AM. Unless otherwise noted below, the samples arrived in good condition, and, where required, properly preserved and on ice.

#### Metals

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

Client Sample ID: 105L-DW-01						Lab San	nple ID: 810-9	7545-1
Date Collected: 03/12/24 06:41							Matrix: Drinkin	g Water
Date Received: 03/18/24 09:00								
	)							
Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.0		0.50	ug/L			03/19/24 14:01	1
Copper	32		1.0	ug/L			03/19/24 14:01	1
Client Sample ID: 105L-DW-02						Lab San	nple ID: 810-9	7545-2
Date Collected: 03/12/24 06:41							Matrix: Drinkin	g Water
Date Received: 03/18/24 09:00								
- Method: EPA 200.8 - Metals (ICP/MS	)							
Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	0.95		0.50	ug/L			03/19/24 14:07	1
Copper	31		1.0	ug/L			03/19/24 14:07	1

#### Job ID: 810-97545-1

Matrix: Drinking Water

Lab Sample ID: 810-97545-1

#### Client Sample ID: 105L-DW-01 Date Collected: 03/12/24 06:41

Date	<b>Received:</b>	03/18/24 09:00	

	Batch	Batch		Dilution	Batch			Prepared
Prep Type	Туре	Method	Run	Factor	Number	Analyst	Lab	or Analyzed
Total/NA	Analysis	200.8		1	92686	NB	EA SB	03/19/24 14:01
Client Samp	le ID: 105L-0	OW-02						Lab Sample ID: 810-97545-2
Date Collected	I: 03/12/24 06:4	1						Matrix: Drinking Wate
Date Received	: 03/18/24 09:0	0						
				<b>B</b> 11 <i>(</i> 1	Batch			Prepared
_	Batch	Batch		Dilution	Datch			
Ргер Туре	Batch Type	Batch Method	Run	Factor		Analyst	Lab	or Analyzed

Laboratory References:

EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

### Laboratory: Eurofins Eaton Analytical South Bend

The accreditations/certifications listed below are applicable to this report.

Authority	Program	Identification Number	Expiration Date
Missouri	State	880	09-30-24

#### Client: Burns & McDonnell Project/Site: GFC

-	
-	
	5
	8
	9

Method	Method Description	Protocol	Laboratory
200.8	Metals (ICP/MS)	EPA	EASB

#### Protocol References:

EPA = US Environmental Protection Agency

#### Laboratory References:

EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

Client: Burns & McDonnell Project/Site: GFC

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
810-97545-1	105L-DW-01	Drinking Water	03/12/24 06:41	03/18/24 09:00
810-97545-2	105L-DW-02	Drinking Water	03/12/24 06:41	03/18/24 09:00

PW-POOL WATER	EW-EXPOSURE WATER	GW-GROUND WATER	DW-DRINKING WATER	MATRIX CODES:	אברוואסטוארבט אדי(אקחמשיפ)		RELINQUISHED BY:(Signature)	(b) (6)	RELINQUISHED BY (Signature)		Ashley Anstaett - alanstaett@burnsmcd.com 9400 Ward Parkway Kansas City, MO 64114	Shaded area for E REPORT TO:	www.EurofinsUS.com/Eaton	810-97545 Chain of Custody
* Please call, expeditec	RW* = Rush Written: (5 working days)	RV* = Rush Verbal: (5 working days)	SW = Standard Written: (15 working days)	TURN-AROUND TIME		AM PM	DATE TIME	3/14 43C	DATE TIME	COLLECTION DATE TIME AM PM 3/2024 0641 X 0641 X	3	EEA use only		Eator
Please call, expedited service not available for all testing	ng days) 75%		(TAT) - SURCHARGES	TURN-AROUND TIME (TAT) - SURCHARGES	(b) (6)	RECEIVED FOR LABORATORY BY:	RECEIVED BY:(Signature)		RECEIVED BY:(Signature)	compliance Monitoring 10チートルーロ 10チーレルーロ	(b) (6)	SAMPLER (Signature)		Eaton Analytical
STAT* = Less than 48 hours	SP* = Weekend, Holiday	IW* =Immedial	) () IV" = Immedial	10 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DALE 03-18 03-18		DATE		DATE	Yes SAMPLING SITE ンクイ ンクイ ンクイ ン ンクイ ン ン			CHAIN OF	
than 48 hours CALL	d, Holiday CALL	IW* =Immediate Written: (3 working days) 125%	IV" = Immediate Verbal: (3 working days) 100%	I VIVI	1900 CONDI	AM PM	TIME	LAB COMMENTS	TIME LAB RESE	NA TEST NAME		91	CUSTODY RECORD	
		Samples received unannounced with less than 48 hours holding time remaining			Iced: Wet/Blue Ambient				LAB RESERVES THE RIGHT TO RETURN UNUSED PORTIONS OF NON-AQUEOUS SAMPLES TO CLIENT	Municipal	-	ATE (sample origin)	IRD	110 S. Hill Street South Bend, IN 46617 T: 1.800.332.4345 F: 1.574.233.8207
	ty be subject to addition				°C Upon Receipt					GFC SAMPLE REMARKS		PROJECT NAME		
	mai charges.	ounced with less			eceiptN/A				JEOUS SAMPLES TO CLIENT	X YES NO   NO # OF CONTAINER:   VES NO   VES VES   VES VES	S	PO#	Page 1 of 1	Order#433311 Batch#

EEA.

0

#### Login Sample Receipt Checklist

Client: Burns & McDonnell

#### Login Number: 97545 List Number: 1 Creator: Pehling-Wright, Penny

Question	Answer	Comment
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
Samples were received on ice.	False	Thermal preservation not required.
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Samples do not require splitting or compositing.	True	
Container provided by EEA	True	

Job Number: 810-97545-1

List Source: Eurofins Eaton Analytical South Bend